

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 02/17/2016
--	--	---	---

NAME OF PROVIDER OR SUPPLIER CAREMOOR RETIREMENT CENTER	STREET ADDRESS, CITY, STATE, ZIP CODE 4876 CAREMOOR PLACE KANNAPOLIS, NC 28081
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	<p>Initial Comments</p> <p>Report of Biennial Construction Survey by Dennis Harrell on 2-17-2016.</p> <p>Records indicate this facility was first licensed on 8-22-1993 for 30 residents. Therefore, we are requiring that this facility meet the 1991 "Regulations for Homes for the Aged and Disabled; Minimum Standards and Regulations, the applicable portions of the 2005 Regulations for Adult Care Homes of Seven or More Beds and the 1991 edition of the North Carolina State Building Code Volume I - General Construction - Section 409 Institutional Occupancy (Group I).</p>	C 000		
C 111	<p>Must Have Current San. & Fire Safety Reports</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review.</p> <p>This Rule is not met as evidenced by:</p> <ol style="list-style-type: none"> 1. Based on review of documents, a current fire alarm inspection report were not available in the home for review. 2. Based on review of documents, the most recent sprinkler inspection report, dated 7-13-2015, indicated deficiencies and no documentation was available to indicate the deficiencies had been corrected. Deficiencies include: <ol style="list-style-type: none"> a. Flow switch damaged and/or electrical connections insecure. b. The ball control valves were not locked or supervised. 	C 111		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 02/17/2016
--	--	---	---

NAME OF PROVIDER OR SUPPLIER CAREMOOR RETIREMENT CENTER	STREET ADDRESS, CITY, STATE, ZIP CODE 4876 CAREMOOR PLACE KANNAPOLIS, NC 28081
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 150	<p>Corridors-Free of equipment and Obstructions</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT</p> <p>(g) The requirements for corridors are: (4) Corridors shall be free of all equipment and other obstructions.</p> <p>This Rule is not met as evidenced by: Based on observation, there was trash in and obstructing the corridor ar the right rear of the facility.</p>	C 150		
C 166	<p>Housekeeping-Maintained Free of Hazards</p> <p>SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS</p> <p>(a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities.</p> <p>This Rule is not met as evidenced by: 1. Based on Observation, the building was not maintained in a safe manner by not properly handling portable medical oxygen cylinders. This could affect all residents, staff and visitors if cylinders fall, breaking their valves, propelling the cylinder and turning it into a dangerous projectile. Findings include: a. One large oxygen cylinder was stored without the required bolt on stabilizing base. b. Several (7) medium portable medical oxygen cylinders were stored in no container. c. Several (20) small portable medical oxygen cylinders were stored in carboard delivery boxes.</p>	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 02/17/2016
--	--	---	---

NAME OF PROVIDER OR SUPPLIER CAREMOOR RETIREMENT CENTER	STREET ADDRESS, CITY, STATE, ZIP CODE 4876 CAREMOOR PLACE KANNAPOLIS, NC 28081
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 2 2. Based on observation there was a double cylinder deadbolt installed on the door to bedroom J. Latching hardware that requires a key to operate from the inside of the room, such as double cylinder deadbolts, present the possibility that someone could be trapped in the room. 3. Based on observation, a cover was missing on an exterior receptacle. Missing covers on exterior electrical outlets allow water to enter and could be hazardous.	C 166		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the facility was not maintained in a safe condition because an exit light was not working. Finding includes: One exit light in the dining room was not working. 2. Based on observation the required one-hour fire rated walls and/or ceilings were compromised in several locations. Holes and penetrations that are not sealed with materials approved for use in	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL013007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 02/17/2016
--	--	---	---

NAME OF PROVIDER OR SUPPLIER CAREMOOR RETIREMENT CENTER	STREET ADDRESS, CITY, STATE, ZIP CODE 4876 CAREMOOR PLACE KANNAPOLIS, NC 28081
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 3</p> <p>one-hour fire rated construction present the possibility that a fire that begins in one space can quickly spread to other areas of the facility. Findings include:</p> <ul style="list-style-type: none"> a. Damaged 1 hour rated attic access door in housekeeping closet, b. Damaged 1 hour rated attic access door in the kitchen, c. Hole in the kitchen ceiling, d. Cardboard patch on the ceiling in the water heater room. <p>3. Based on observation, many corridor doors are prevented from closing quickly or do not latch or properly fit the door frame to resist the passage of fire and smoke. Corridor doors that do not close completely and latch present the possibility that a fire that begins in one space can quickly spread to the corridor and the remainder of the facility. Findings include;</p> <ul style="list-style-type: none"> a. The door to the beauty parlor was wedged open, b. The door to the clean linen room was wedged open, c. The door to the laundry was propped open with a tub of clothes, d. The door to bedroom PA would not latch when closed. e. The door to bedroom KR would not latch when closed. f. One dining room door was wedged open, g. The other dining room door was propped open. h. Several corridor doors had sagged and were not fitting the frame at the top to be smoke resisting, i. Several bedroom doors were not closing against the door stop to be smoke resisting, 	C 189		